


WHISPERFLO® VST

REPLACEMENT PARTS



Item	Part No.	Description	US List	Can-List	Item	Part No.	Description	US List	Can-List
WHISPERFLO VST									
1	357199Z	Lid Clamp	76.56	91.99	20	071131z	Drain Plug, 2 Req.	9.85	11.84
2	357151Z	Lid	57.49	69.08	21	192115	O-ring, Drain Plug, 2 Req.	CALL	CALL
2	357156	Lid, Chemical Resistant	108.44	130.30	22	357149	Strainer Pot/Seal Plate Kit, (Incl. Items: 1-4, 9, 10, 16, 18, 24, and 25)	480.93	577.89
3	350013z	O-ring, Lid	6.04	7.26	23	073130Z	Impeller	160.28	192.59
4	070387z	Strainer Basket	26.77	32.17	24	356279	Drive Cover	502.91	604.30
5	070430Z	Bolt, 3/8 - 16 x 1-1/4 Hex Head, SS, 4 Req.	4.02	4.83	25	356282	Drive Kit	1637.19	1967.25
6	072184	Washer, 3/8 x 7/8 O.D. SS, 6 Req.	2.48	2.98	26	356286s	Motor	927.24	1114.17
7	357100z	Gasket, Seal Plate	10.34	12.42	27	356289s	Motor/Drive Assembly	2172.76	2610.79
8	350015Z	Strainer Pot	366.49	440.37	NOT SHOWN				
9	355227z	O-ring, Diffuser	5.21	6.26	075455	Fluid Assembly, (Incl. All Items EXCEPT 31)	CALL	CALL	
10	072927z	Diffuser	121.74	146.28	357243Z	Strainer Pot Assembly, (Incl. Items 1-4, 10, 24 and 25)	764.82	919.01	
11	071652z	Impeller Screw, 1/4 - 20 x 1 in., LH, Phillips	5.03	6.04	356324z	RS-485 Automation Wiring Kit	120.32	144.58	
12	075713Z	Washer, Impeller Screw	2.89	3.47	357923z	Motor Fan Guard Kit	CALL	CALL	
13	071734s	Shaft Seal, PA-7 w/ Ceramic Seat, PS1000	48.53	58.31					
14	071732s	Shaft Seal, Ozone/Salt Resistant	40.66	48.86					
15	070429z	Bolt, Motor/Seal Plate, 4 Req.	5.03	6.04					
16	350202	Seal Plate Kit (Shaft Seal Installed) (Incl. Items 9, 16 & 18)	322.49	387.50					
17	070927Z	Motor Foot	61.41	73.79					
18	070929Z	Insert, Motor Foot	30.82	37.03					
19	071406Z	Nut, Motor Foot, 2 Req.	2.60	3.12					

CALIFORNIA PROPOSITION 65 WARNING

⚠️ **WARNING:** Cancer and Reproductive Harm.
 ⚠️ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠️ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov